

1/12




FIG. 1A
(PRIOR ART)




FIG. 1B
(PRIOR ART)




FIG. 1C
(PRIOR ART)

For 504 462 8500

2/12




FIG. 2A
(PRIOR ART)




FIG. 2B
(PRIOR ART)

3/12




FIG. 3A
(PRIOR ART)




FIG. 3B
(PRIOR ART)




FIG. 3C
(PRIOR ART)

4/12




FIG. 4A
(PRIOR ART)




FIG. 4B
(PRIOR ART)

5/12




FIG. 5A




FIG. 5B




FIG. 5C

6/12




FIG. 6A




FIG. 6B

7/12




FIG. 7A




FIG. 7B




FIG. 7C

8/12




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D

9/12




FIG. 9A




FIG. 9B




FIG. 9C

10/12




FIG. 10A




FIG. 10B




FIG. 10C

11/12




FIG. 11A




FIG. 11B




FIG. 11C

